



DEFENSE NUCLEAR AGENCY  
ARMED FORCES RADIOBIOLOGY RESEARCH INSTITUTE  
BETHESDA, MARYLAND 20014

79-02  
(50-170)

DIR

AUG 01 1979

Director, Region 1  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

Dear Sir:

This letter transmits a report of a malfunction of the fuel element temperature sensing circuit.

My staff will provide any additional information that may be required.

Sincerely,

*Paul E. Tyler*  
PAUL E. TYLER  
Captain, MC, USN  
Director

1 Encl  
as stated

A020

611 351

7908100 439