

BOSTON EDISON COMPANY

TELECOPY MESSAGE

To: 215-337-5272
Telephone Number

Date/Time: Aug. 9, 1979 0900

To: Director, Region I
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

From: Pilgrim Nuclear Power Station
RFD #1 Rocky Hill Road
Plymouth, MA 02360

Subject: PROMPT REPORTABLE OCCURRENCE
Docket Number 50-293; License DPR-35

Assigned LER Number 79-029/01X-0

Event Description: On June 12, 1979 while performing repairs on the "A" Core Spray
System minimum flow line, a degradation of primary containment integrity occurred.
This is a violation of Tech. Spec. 3.7.A.2.

Cause and Corrective Action: While investigating problems with the Core Spray Loop "A"
minimum flow line, the disc in the 6" check valve required repair and was removed
and replaced, thus violating primary containment integrity. This occurrence was
identified during an unscheduled IE Inspection.

Facility Status:

c) Routine Startup _____
d) Routine Shutdown _____
e) Steady State X _____
f) Load Changing _____

100 % Thermal MW

g) Shutdown _____
h) Refueling _____
i) Other _____
j) Not Applicable _____

A written follow-up report will be sent within two weeks.

NRC person notified Mr. R. Architzel

Prepared by John M. Fulton

Mail (2) copies to:

Director
Office of Management Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

7908140 547

A002
9/10