

TEXAS UTILITIES GENERATING COMPANY

2001 BRYAN TOWER - DALLAS, TEXAS 75201

July 2, 1979
TXX-3007

R. J. GARY

EXECUTIVE VICE PRESIDENT
AND GENERAL MANAGER

Mr. W. C. Seidle, Chief
Reactor Construction and
Engineering Support Branch
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
611 Ryan Plaza Dr., Suite 1000
Arlington, Texas 76011

Docket Nos. 50-445
50-446

COMANCHE PEAK STEAM ELECTRIC STATION
1981-83 2300 MW INSTALLATION
UNIT NO. 1 REACTOR VESSEL NOZZLE
WELD METAL DEFECTS
FILE NO. 10110

Dear Mr. Seidle:

On January 26, 1979, we verbally informed your Mr. W. A. Crossman of apparent weld metal defects in the shop weld between the Unit No. 1 reactor pressure vessel hot leg nozzle "C" and its safe end that we were evaluating as "potentially" reportable within the definition of 10 CFR 50.55 (e). We have completed our investigation and have concluded that the matter is not reportable under 10 CFR 50.55 (e). Records supporting this determination are available for your Inspector's review at the CPSES site.

If you have any further questions, please advise.

Very truly yours,

R. J. Gary
R. J. Gary

RJG:ljj

cc: NRC Region IV - (0 + 1 copy)

Director, Inspection & Enforcement - (15 copies)
c/o Distribution Services Branch, DDC, ADM.
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

7907 110 346

314 002