

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N C B E P 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
7 8 9 14 15 25 26 30 57 CAT 58

CON'T  
0 1 REPORT SOURCE L 6 0 5 0 - 0 3 2 5 7 0 5 0 4 7 9 8 0 7 0 9 7 9 9  
7 8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal reactor startup, the operator noticed that he did not have either  
0 3 "full in" or "full out" indication on rod 22-47. The individual rod position indica-  
0 4 tion system was working for rod position indication of that rod. Subsequent reactor  
0 5 startups have not had this problem.  
0 6 (Technical Specification 3.1.3.7b, 6.9.1.9b)  
0 7  
0 8

0 9  
7 8 9  
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE  
I D 11 X 12 Z 13 I N S T R U 14 X 15 Z 16  
9 10 11 12 13 18 19 20  
17 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.  
7 9 0 2 8 0 3 X 1  
21 22 24 26 27 28 29 30 31 32  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
X 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 N 24 N 25 G 0 8 0 0 26  
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The circuitry for both "full in" indication and "full out" indication was checked with  
1 1 no problem found. These indications now indicate normally. This is considered an  
1 2 isolated event and no further action is required.  
1 3  
1 4

1 5 FACILITY STATUS C 28 % POWER 0 4 6 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Surveillance 32  
7 8 9 10 11 12 13 44 45 46 80  
1 6 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36  
7 8 9 10 11 44 45 80  
1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39  
0 0 0 37 Z 38 NA  
7 8 9 11 12 13 80  
1 8 PERSONNEL INJURIES NUMBER DESCRIPTION 41  
0 0 0 40 NA  
7 8 9 11 12 80  
1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43  
Z 42 NA  
7 8 9 10 80  
2 0 PUBLICITY ISSUED DESCRIPTION 45  
N 44 NA  
7 8 9 10 80

361 069  
7907130 345 S

NAME OF PREPARER A. C. Tollison, Jr.

PHONE: 919-457-9521