

CENTRAL FILES

BOSTON EDISON COMPANY

TELECOPY MESSAGE

215 337-5324
Telephone Number

Date/Time: July 11, 1979 1100

Director, Region I
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

From: Pilgrim Nuclear Power Station
RFD #1 Rocky Hill Road
Plymouth, MA 02360

Subject: PROMPT REPORTABLE OCCURRENCE
Docket Number 50-293; License DPR-35
Assigned LFR Number 79-021/01X-0

POOR ORIGINAL

Event Description: On July 10, 1979, during performance of maintenance in the steam
tunnel area, water was observed dripping from lagging on the CRD return line. The
lagging was removed and a small leak was discovered in the area of the inboard weld
on the inboard manual isolation valve. This leak is within the reactor coolant pressure
boundary.
Cause and Corrective Action: Cause is unknown at this time. Visual surveillance of
the area was increased to every four (4) hours and plans are in progress for shutting
down for repairs.

Reactivity Status:	80 <input checked="" type="checkbox"/> Thermal MW
Routine Startup _____	g) Shutdown _____
Routine Shutdown _____	h) Refueling _____
Steady State _____	i) Other _____
Load Changing <input checked="" type="checkbox"/> _____	j) Not Applicable _____

Written follow-up report will be sent within two weeks.

Person notified Mr. T. Stedtka Prepared by Mr. C. J. Mathis

(2) copies to:
Director
Office of Management Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

7907190323

324 003