

Georgia Power Company  
230 Peachtree Street  
Post Office Box 4545  
Atlanta, Georgia 30303  
Telephone 404 522 6080

TIC



Georgia Power

Power Supply Engineering and Services

June 22, 1979

United States Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303

REFERENCE:  
RII: JPO  
50-321  
50-366

ATTENTION: Mr. James P. O'Reilly

Gentlemen:

The following information is submitted as a follow-up to our letter of April 16, 1979, responding to IE Bulletin 79-03.

The special ultrasonic examinations of the 12" recirc "A" loop jet pump risers, as referenced in our response to IE Bulletin 79-03, have been completed by Southwest Research Institute on Unit 1. Although the material used in the recirc system was not of the same grade as specified in the IE Bulletin, special examinations were performed for informational purposes only, because the material was manufactured by the same company. There were no recordable indications found as a result of the special examinations on the Youngstown Welding & Engineering manufactured seam welded stainless steel piping. Southwest Research Institute examination summary sheets are enclosed for your information. Due to their quantity, the corresponding data sheets are not enclosed but are available at the plant site for your review.

Should you have any questions, please contact my office.

Very truly yours,

R. W. Staffa  
Manager of Quality Assurance

JAB/vg  
Enclosures

446 245

7908020

7908020251

790252  
OFFICIAL CO.