

NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

June 4, 1979

Mr. James G. Keppler
Director - Region III
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137


Dear Mr. Keppler:

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Dockets No. 50-282 and No. 50-306

In response to IE Bulletin 79-11, the following information is offered:

The only breakers of the type described in use in safety-related systems are the reactor trip breakers; these do not have the overcurrent trip feature.

Yours very truly,



L. J. Wachter
Vice President
Power Production and
System Operation

cc: Mr. G. Charnoff

06 1979

7908070048

401 345 ①