

TIC

CP&L
USING
Carolina Power & Light Company

July 12, 1979

79 JUL 17 A 9: 36

FILE: NG-3513 (B)

SERIAL: GD-79-1698

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, GA 30303

BRUNSWICK STEAM ELECTRIC PLANT, UNIT NOS. 1 & 2
LICENSE NOS. DPR-71 AND DPR-62
DOCKET NOS. 50-325 AND 50-324
RESPONSE TO IE BULLETIN 79-11


Dear Mr. O'Reilly,

In response to your letter of May 22, 1979, transmitting IE Bulletin 79-11 concerning faulty overcurrent trip devices in circuit breakers for ESF systems, Carolina Power & Light Company submits the following information:

An extensive search of plant documentation indicates that no Westinghouse Type DB-50 or DB-75 breakers are used in safety-related class IE service or are maintained as spares at the Brunswick Steam Electric Plant.

We trust that this information satisfies the request of IE Bulletin 79-11.

Yours very truly,



E. E. Utley
Executive Vice President
Power Supply & Customer Services

RMP/DCS/mls*

500 361