



NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

June 29, 1979

Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr Keppler:

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket No. 50-282 License No. DPR-42

Missed SP1187 in January 1979

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 4.16.B.1a.1 in that the weekly required surveillance test was missed.

Yours very truly,



L O Mayer, PE
Manager of Nuclear Support Services

LOM/JAG/jh

cc: Director, IE, USNRC (30)
Director, MIPC, USNRC (3)
MPCA
Attn: J W Ferman

-over-

7907050404

281 106

*Hook
5/11*