



**LOUISIANA**  
**POWER & LIGHT**

142 DELARONDE STREET  
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

August 1, 1979



LPL 11698  
Q-3-A35.07

Mr. K.V. Seyfrit, Director, Region IV  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012

SUBJECT: Waterford SES Unit 3  
Docket No. 50-382  
Potential Incident No. 21  
Rosemount 1153 Series A Pressure Transmitters

Dear Mr. Seyfrit:

This is to confirm the telecon on July 31, 1979 between your Mr. W.G. Hubacek and our Mr. T.F. Gerrets. LP&L has completed a preliminary review of the hardware anomaly and the relationship of the anomaly to Waterford 3. Our preliminary findings do not indicate any safety problems existing at Waterford 3. We are in the process of formalizing our review and the conclusion reached. This review should be complete by September 28, 1979 and we will notify you of the results of the review on or before that date.

Yours very truly,

D.L. Aswell

DLA/TFG/ys

7909040057

901001