

INSEL EVENT REPORT

CONTROL BLOCK: [] [] [] [] [] [] [] [] [] []

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	C	T	M	N	S	2	7	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4			5	
R		LICENSEE CODE					14	15	LICENSE NUMBER								25	26	LICENSE TYPE					30	57	CAT 58	

CONT

0	1	L	6	0	5	0	0	0	3	3	6	7	0	7	2	7	7	9	8	0	8	2	4	7	9	9
		REPORT SOURCE	DOCKET NUMBER										EVENT DATE					REPORT DATE								
		60	61	68										74					80							

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During routine plant operation CEA 64 position indication was declared inoperable

0 3 | due to erratic indication. CEA 64 was verified to be fully withdrawn by its

0 4 | top limit indication and operation continued in accordance with technical spec-

0 5 | ifications, Section 3.1.3.3, Action Statement C.

[illegible]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)