

VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

September 21, 1979

Mr. Harold R. Denton, Director
Office of Nuclear Reactor Regulation
Attention: Mr. O. D. Parr, Chief
Light Water Reactors Branch No. 3
Division of Project Management
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Serial No. 756/090779
LQA/ESG:pw
Docket No. 50-339

Dear Mr. Denton:


GUIDE THIMBLE TUBE WEAR

We have reviewed Mr. Parr's letter of September 7, 1979, which requested additional information concerning Westinghouse experience with guide thimble tube wear. Since these requests pertain to generic information previously provided to you by Westinghouse, we believe that the information requested would be most appropriately developed on a generic basis.

It is our understanding that Westinghouse is currently developing these responses to your requests and is planning to provide these generic responses within approximately two weeks. We will follow the efforts of Westinghouse in providing these responses and will review the generic responses to verify their applicability to North Anna Unit 2.

Please contact us should you require additional information or clarification.

Very truly yours,



W. N. Thomas
Vice President
Fuel Resources

7909260447

Boo1
SE
1/0

771352