



TIC John Rausch  
MISSISSIPPI POWER & LIGHT COMPANY

Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

PRODUCTION DEPARTMENT

July 20, 1979

Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street - Suite 3100  
Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Director

Gentlemen:

70 SEP 7 A10:59  
USNRC REGION II  
ATLANTA, GA 30303  
SUBJECT: Grand Gulf Nuclear Station  
File 0260/15521/L-860  
Evaluation of IE Bulletin 79-11  
AECM-79/77

We have completed our review of IE Bulletin 79-11 entitled "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Systems." We have determined that Grand Gulf Nuclear Station does not use the DB-75 and DB-50 type circuit breakers as referenced in the bulletin. Based on this finding, we are planning no further action in response to this bulletin.

POOR  
ORIGINAL

Yours truly,

L. F. Dale  
Nuclear Project Manager

RTE/pa

cc: Mr. N. L. Stampley  
Mr. R. B. McGehee  
Mr. T. B. Conner

Mr. John G. Davis, Director  
Division of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

bcc: Dr. D. C. Gibbs  
Mr. Adrian Zaccaria  
Mr. J. N. Ward  
Mr. D. M. Lake  
Mr. R. L. Scott  
Mr. J. P. McGaughy, Jr.  
Mr. W. L. Nail  
Mr. T. E. Reaves ← THIS COPY FOR  
Mr. C. K. McCoy  
Mr. P. W. Sly  
File

7910010243