



Commonwealth Edison
One First National Plaza, Chicago, Illinois
Address Reply to: Post Office Box 767
Chicago, Illinois 60690

September 25, 1979

Mr. Roby Bevan, Jr.
Operating Reactors - Branch 2
Division of Operating Reactors
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Subject: Quad-Cities Station Units 1 and 2
Fire Protection Modifications
NRC Docket Nos. 50-254 and 50-265

Dear Mr. Bevan:

Item 5.21 of the Quad-Cities Fire Protection Safety Evaluation Report (SER) dated July 27, 1979 describes a lubricating oil storage hazard in the Crib House consisting of nine 55-gallon drums of lubricating oil. The item also describes a proposed modification (5.21.6) to the area to protect against the hazard. Paragraphs 3.1.5 and 3.1.11 list the modification to the Crib House to protect against this hazard consisting of a water sprinkler system, curbs and drains in the oil storage area.

The Crib House Oil Storage Area has been reviewed again and, based on the results of this review, the oil barrels will be removed. A flammable liquid cabinet will be installed. The cabinet will not contain more than 25 gallons of oil and 10 gallons of grease. The oil and grease will be stored in 5-gallon cans.

Based on the reduced level of oil storage, it will, therefore, not be necessary to install a sprinkler system, curbs or drains in the Crib House Oil Storage Area.

Please address any questions you may have concerning this matter to this office.

One (1) signed original and thirty-nine (39) copies of this transmittal are provided for your use.

Very truly yours,

for *H. J. Naughton*
Robert F. Janacek
Nuclear Licensing Administrator
Boiling Water Reactors

RFJ:mae

7910020 379

1078 140