



Consumers
Power
Company

Stephen H. Howell
Senior Vice President

General Offices: 1945 West Parnall Road, Jackson, Michigan 49201 • (517) 788-0453

September 28, 1979
Howe-254-79

Mr J G Keppler, Regional Director
Office of Inspection and Enforcement
US Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

MIDLAND NUCLEAR PLANT -
UNIT NO 1, DOCKET NO 50-329
UNIT NO 2, DOCKET NO 50-330
CONTAINMENT BUILDING PRESTRESSING TENDONS

Reference: S H Howell letter to J G Keppler; Midland Nuclear Plant;
Unit No 1, Docket No 50-329; Unit No 2, Docket No 50-330;
Containment Building Prestressing Tendons; Serial Howe-226-79;
dated August 23, 1979

The referenced letter was an interim 50.55(e) report, as is this letter, on
tendon wires which were in nonconformance to length requirements. The
enclosure provides the status of resolution of this condition.

Another report, either interim or final, will be sent on or before
October 31, 1979.

Stephen H. Howell

WRB/lr

Enclosure: MCAR-33, Interim Report #2, dated September 10, 1979

CC: Director of Office of Inspection and Enforcement
Att: Mr Victor Stello, USNRC (15)

Director, Office of Management
Information and Program Control, USNRC (1)

1071 165

7910020

498