



TK

## Omaha Public Power District

1623 HARNEY ■ OMAHA, NEBRASKA 68102 ■ TELEPHONE 536-4000 AREA CODE 402

August 29, 1979

Mr. K. V. Seyfrit, Director  
U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region IV  
611 Ryan Plaza Drive  
Suite 1000  
Arlington, Texas 76011

Re: Docket No: 50-285

Dear Mr. Seyfrit:

The Omaha Public Power District received IE Bulletin 79-06 C, dated July 26, 1979, regarding the operation of reactor coolant pumps after initiation of an accident. In order to address the concerns of items 2 and 3 (short term actions) and item 1 (long term actions) of the Bulletin, the District has participated in a Combustion Engineering User's Group. Accordingly, a response to these items was provided on behalf of the User's Group to the Commission in a letter, dated August 29, 1979 from Mr. G. Liebler, which included the report CENPD-115-P.

In response to item 4 (short term actions) the District is currently evaluating emergency procedures and licensed reactor operator training as related to our response to the aforementioned items. Implementation of revised procedures and training will depend upon the Staff's evaluation of our response.

Sincerely,

*T. E. Short*  
for T. E. Short

Assistant General Manager

TES/BJH/rh

xc: Director, Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Director, Office of Nuclear Reactor Regulations  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

LeBoeuf, Lamb, Leiby & MacRae  
1333 New Hampshire Avenue, N.W.  
Washington, D. C. 20036

1069 084

7910020635

Q