



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

September 7, 1979

D. L. ASWELL
Vice President-Power Production

LPL 11960
Q-3-A20.03.18
3-A1.01.04

U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Washington, D. C. 20555

ATTENTION: Director, Division of Reactor
Construction Inspection

SUBJECT: Waterford SES Unit 3
Docket No. 50-382
I. E. Bulletin 79-15

Dear Mr. Seyfrit:

We have reviewed the subject bulletin and have found that vertical turbine pumps with impellers located in bowls in a sump or a self contained barrel, are not used on Waterford SES Unit No. 3.

In view of the above, no additional information is provided.

If you have any questions, please advise.

Yours very truly,

D. L. Aswell

DLA:JFK:smd

cc: Mr. Karl V. Seyfrit, Director Region IV
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

1202 173

7910240 031