



**LOUISIANA**  
POWER & LIGHT

142 DELARONDE STREET  
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

September 14, 1979

D. L. ASWELL  
Vice President-Power Production

LPL 11994  
Q-3-A35.02.01  
Q-3-A35.07

Mr. K. V. Seyfrit, Director, Region IV  
U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76012

SUBJECT: Waterford SES Unit #3  
Interim Report of Significant Construction  
Deficiency Number 13  
Reactor Containment Building  
Dome Concrete

Dear Mr. Seyfrit:

In accordance with the requirements of 10CFR50.55(e), we are submitting two (2) copies of the Interim Report for the subject Significant Construction Deficiency No. 13. Additionally as previously agreed to, you will be notified 48 hours prior to the resumption of placement of concrete in the containment building dome.

Yours very truly,

D. L. Aswell

DLA:TFG:smd

Enclosures

- cc: 1) Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555  
(with 15 copies of report)
- 2) Director  
Office of Management  
Information and Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555  
(with one copy of report)

1202 290

7910240106