

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

October 18, 1979

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNIT 1 - FLEXIBLE BELLOWS PENETRATIONS OF STEEL  
CONTAINMENT VESSEL MISALIGNED DURING INSTALLATION - NCR 1666 -  
REVISED FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector  
W. T. Cottle on May 25, 1979, in accordance with 10 CFR 50.55(e).  
An interim report was submitted on June 25, 1979. A final report  
was submitted on September 11, 1979. Enclosed is our revised final  
report.

If you have any questions concerning this matter, please get in touch  
with D. L. Lambert at FTS 854-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager  
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Jr., Director (Enclosure) ✓  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

1207 024

Boig  
S. 11

638