

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	C	B	E	P	1	2	0	0	-	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4	5		
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE				30	57	CAI	58

REPORT SOURCE: 01 L 6 0 5 0 - 0 3 2 5 7 1 0 0 4 7 9 8 1 0 2 9 7 9 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | While performing PT 1.1.4PC Reactor Low Level I Channel Calibration, level instruments |

03 | 1B21-LIS-NO17 A, switch 1, and 1B21-LIS-NO17 C, switch 1, were out of tolerance. The

04 | value for NO17A was 3.95" water with a limit of ≥ 12.5 " water, and the value for NO17C

05 was 1.113" water with a limit of ≥ 12.5 " water.

06 | Technical Specifications 2.2.1, 6.9.1.9a

0	7	
---	---	--

08

SYSTEM CODE I A 11		CAUSE CODE E 12		CAUSE SUBCODE G 13		COMPONENT CODE I N S T R U 14		COMP. SUBCODE Y 15		VALVE SUBCODE Z 16	
LER/RO REPORT NUMBER 7 9 17		EVENT YEAR 7 9 21 22		SEQUENTIAL REPORT NO. 0 8 0 24 26		OCCURRENCE CODE 0 3 28 29		REPORT TYPE L 30		REVISION NO. 0 32	
ACTION TAKEN E 18		FUTURE ACTION C 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22		ATTACHMENT SUBMITTED N 23	
NPRD-4 FORM SUB. Y 24		PRIME COMP. SUPPLIER N 25		COMPONENT MANUFACTURER B 0 8 0 26							

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The out of tolerance values were attributed to instrument drift. The instruments were

11 recalibrated and returned to service. This instrumentation is being replaced during

1 2 | the 1980 refueling outage to provide more reliable instrumentation.

1	3	
---	---	--

1	4	
---	---	--

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

FACILITY STATUS (28) 1 5 E

% POWER 0 9 6 (29) NA

OTHER STATUS (30)

METHOD OF DISCOVERY (31) B Periodic Test

DISCOVERY DESCRIPTION (32)

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 Z (33) Z (34) NA NA

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	NA	(39)

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	NA

1280 346

		LOSS OF OR DAMAGE TO FACILITY		
		TYPE	DESCRIPTION	
1	9	Z	(42) NA	(43)

ISSUED DESCRIPTION (45) 7911010 407 NRC USE ONLY

NAME OF PREPARER A. C. Tollison, Jr.

PHONE: 919-457-9521