



Georgia Power Company  
Plant E. I. Hatch  
Baxley, Georgia 31513

Event Description and Probable Consequences (continued)

There were no effects upon the public health and safety due to these events.

Cause Description and Corrective Actions (continued)

For the event on 10-12-79, the SJAE was taken out of service and system drained of excess water. SJAE was then returned to service. For the event on 10-18-79, the SJAE drain tank air operated eductor valves were cycled several times with their control switches and then they started working properly. The Engineering Department is currently reviewing the SJAE and offgas systems operating procedures for possible procedural and/or design changes to improve operation of these systems.

1276.022