

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	0	5	0	0	0	3	4	8	7	1	0	2	7	7	9	8	1	1	2	0	7	9	9	
62	61	DOCKET NUMBER						68	63	EVENT DATE						74	75	REPORT DATE						80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 0810 on 10-27-79, the Containment Air Lock Personnel Access Hatch was declared  
0 3 | inoperable due to it's failure to meet the acceptance criteria (no detectable leakage)  
0 4 | of surveillance test FNP-0-STP-15.0. Tech. Spec. 3.6.1.3 requires the containment air  
0 5 | locks to be operable. Tech. Spec. 3.6.1.3 action statement requirements were met. A  
0 6 | similiar occurrence was reported in LER 79-008/03L-0. The health and safety of the  
0 7 | public were not affected by this event.

03 | \_\_\_\_\_ 8

7 8      SYSTEM CODE      CAUSE CODE      CAUSE SUBCODE      COMPONENT CODE      COMP. SUBCODE      VALVE SUBCODE

0 9      S A (11)      E (12)      X (13)      P E N E T R (14)      A (15)      Z (16)

9 10      11      12      13      14      15      16

(17) LER-RO REPORT NUMBER EVENT YEAR 7 9 — SEQUENTIAL REPORT NO. 0 4 2 / OCCURRENCE CODE 0 3 REPORT TYPE L — REVISION NO. 0

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS				ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER			
A	13	Z	10	Z	20	Z	21	0	0	0	0	N	23	N	24	A	25	C	1	3	0
33		34		35		36		37			40	41		42		43		44			47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 This occurrence was a result of a leaking exterior door seal. The seal was replaced  
1 1 and FNP-0-STP-15.0 was successfully performed. The hatch was declared operable at  
1 2 1627 on 10-27-79.

1	3	
---	---	--

1 4 2 8 9 86

FACILITY STATUS				S. POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION		
1	5	G	(28)	0	0	0	(29)	NA	B	(31)	Performance of surveillance test		
2	8	9		10		12	(29)	13	44	45	(31)	46	80

ACTIVITY CONTENT  
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)

1 6 2 (33) 2 (34) NA

7 8 9 10 11 44

LOCATION OF RELEASE (36)

NA

45 80

PERSONNEL EXPENDITURES									
NUMBER		TYPE		DESCRIPTION					
1	2	0	0	0	(39)	Z	(38)	NA	

7 8 9 11 12 13 80


PERSONNEL INJURIES

NUMBER		DESCRIPTION		UNIT	QUANTITY	PRICE	TOTAL
1	000	40	NA				DOOR ORIGINAL

LOS OF OR DAMAGE TO FACILITY (43)

TYPE		DESCRIPTION		NA		1388 115	
1	9	Z	42				

7911230 304 NRC USE ONLY


 2 9 N 10 NA 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

NAME OF THE PARTY: W. G. Hairston, III

PHONE: (205) 899-5156

NRC USE ONLY