

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

November 15, 1979

Mr. James R. O'Reilly, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNIT 1 - VIBRATION IN RHR PIPING - NCR CEB 79-4 -  
FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector C. R. McFarland on February 8, 1979, in accordance with 10 CFR 50.55(e). Interim reports were submitted on March 9, 1979, May 8, 1979, and July 11, 1979. The interim reports on this nonconformance inadvertently indicated it applied to both units 1 and 2. Please disregard the applicability to unit 2. Enclosed is our final report.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 854-2531.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager  
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Jr., Director (Enclosure) ✓  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

1406 068

Bol  
5/11

2911280

407