

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401  
400 Chestnut Street Tower II

August 31, 1979

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNITS 1 AND 2 - CORROSION OF CABLE  
TERMINATIONS IN JUNCTION BOXES INSIDE CONTAINMENT - NCR 9P -  
FINAL REPORT

The subject deficiency was initially reported to NRC-OIE  
Inspector W. T. Cottle on June 27, 1979, in accordance with  
10 CFR 50.55(e). An interim report was submitted July 24,  
1979. Enclosed is our final report.

If you have any questions concerning this matter, please get  
in touch with D. L. Lambert at FTS 854-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

*(Signature)*  
L. M. Mills, Manager  
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Jr., Director (Enclosure) ✓  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

938 197

7909110 4505