

TIC

TEXAS UTILITIES GENERATING COMPANY

P. O. BOX 1002 · GLEN ROSE, TEXAS 76043

September 17, 1979

Mr. K.V. Seyfrit, Director
U.S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Docket Nos. 50-445
50-446

COMANCHE PEAK STEAM ELECTRIC STATION
1981-83 2300 MW INSTALLATION
OMMISSION OF SHEAR TIE REINFORCING STEEL
UNIT NO. 2 - REACTOR CONTAINMENT BUILDING
FILE NO. 10110

Dear Mr. Seyfrit:

This letter transmits our formal report concerning the inadvertent omission of shear tie reinforcing steel from the 32nd lift of the Comanche Peak, Unit No. 2 Reactor Containment Building (RCB) exterior wall just below the springline. This report responds to the actions contained in your letter of September 7, 1979 summarizing our telephone conversation of that date with Mr. W.C. Siedle of your office.

Based on our review of the matter as summarized in the attached report, we plan to resume concrete placement on the Unit No. 2 Reactor Containment Building Exterior Wall and Dome on September 18, 1979. If you have any further questions, please advise.

Very truly yours,

R.G. Gary
R.G. Gary

RJG:lsm
CC: L.F. Fikar

1506 037

7912060 595