

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

December 5, 1979

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNITS 1 AND 2 - FIRE EXTINGUISHERS NOT  
SEISMICALLY SUPPORTED - NCR MEB 79-43 - FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector  
F. S. Cantrell on November 5, 1979, in accordance with 10 CFR 50.55(e).  
Enclosed is our final report.

If you have any questions concerning this matter, please get in touch  
with D. L. Lambert at FTS 854-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager  
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Jr., Director (Enclosure) ✓  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

1541 074

7912120477

B019  
SE  
1/1

5