

SEABROOK STATION
Engineering Office:
20 Turnpike Road
Westborough, MA 01581

December 6, 1979

SBN-107
T.F. Q 2.2.2

U.S. Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Attention: Office of Inspection and Enforcement


Reference: 1. Docket No. 50-443 and 50-444
2. Telecon of 11/ 6/79 between J. Mattia NRC and
John DeVincentis YAEC

Subject: 10 CFR 50.55 (e) Report on Discrepancy in Drawings with
Respect to Design Calculation Concrete Reinforcement
Requirements for the Control and Diesel Generator Buildings

Dear Sir:

The enclosed report is submitted in accordance with the requirements
of 10 CFR 50.55 (e). This deficiency was reported to the Region I Inspection
and Enforcement office, by telephone, on 11/ 6/79.

Very truly yours,


John DeVincentis
Project Manager

JDV:tla

Enclosure

cc: Director of Inspection & Enforcement
U.S. NRC, Washington, D.C.

1541 094

7912120 486 S 1/1

8019
SE