

BOSTON EDISON COMPANY

TELECOPY MESSAGE

To: 1-215-337
Telephone Number

Date/Time: 10/10/79 / 1000

To: Director, Region I
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

From: Pilgrim Nuclear Power Station
RFD #1 Rocky Hill Road
Plymouth, MA 02360

Subject: PROMPT REPORTABLE OCCURRENCE
Docket Number 50-293; License DPR-35

Assigned LER Number 79-039/01X-0

Event Description: At 1215 hours on 10/9/79, Bechtel Corporation notified BECo
that reanalysis of as built configuration of "B" RBCCW indicated that, analytically,
the system would not remain functional during SSE.

Cause and Corrective Action: This event resulted from a design error. Three supports
are presently being modified to return the system to its original design criteria.

Facility Status:

c) Routine Startup _____
d) Routine Shutdown _____
e) Steady State X
f) Load Changing _____

80 % Thermal MW
g) Shutdown _____
h) Refueling _____
i) Other _____
j) Not Applicable _____

A written follow-up report will be sent within two weeks.

NRC person notified Mr. Ralph Architzel

Prepared by Mr. C. J. Mathis

Mail (2) copies to:

Director
Office of Management Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

1157 041

7910170 268

M007
5/10

5