

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | V | T | V | Y | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

7 8 9 14 15 25 26 30 57 CAT 58

LICENSEE CODE LICENSE NUMBER LICENSE TYPE

CON'T

CON 1

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	2	7	1	7	0	9	2	5	7	9	8	1	0	2	4	7	9	9
60	61								68	69							74	75						80
DOCKET NUMBER										EVENT DATE										REPORT DATE				

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | While performing the refuel outage setpoint check of two of the main steam safety/  
0 3 | relief valves in accordance with Tech. Spec. Section 4.6.D.2, S/N 67HH13 had an as-  
0 4 | found setpoint of 1088 psig. Tech. Spec. Section 2.2.B requires that the setpoint be  
0 5 | ≤1080 psig. As a result of this event, there were no consequences to the health and  
0 6 | safety of the public. A similar occurrence was reported to the Commission as  
0 7 | RO 78-10/3L.

08		7		8		9		80							
SYSTEM CODE				CAUSE CODE		CAUSE SUBCODE		COMP. SUBCODE				VALVE SUBCODE			
C		C		E		B		V A L V E X				Y			
9		10		11		12		13				14			
0		9		17		18		19				20			
7		8		11		12		13				14			
EVENT YEAR				SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.					
7		9		0		2		7		0		3			
21		22		23		24		25		26		27			
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.			
E		Z		Z		Z		0		Y		Y			
18		19		20		21		22		23		24			
23		24		25		26		27		28		29			
PRIME COMP. SUPPLIER				COMPONENT MANUFACTURER											
N		T		0		2		0							
43		44		45		46		47							

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of this occurrence is attributed to setpoint drift. The valve was dis-

1 1 assembled, discs and seats lapped, reassembled, and adjusted to the proper setpoint.

1 2 The valve was manufactured by Target Rock Corporation, Model 67F.

1 3

1 4 7 8 9 FACILITY STATUS 30 OTHER STATUS 31 METHOD OF DISCOVERY 32 DISCOVERY DESCRIPTION 33

1 5 7 8 9 H 28 10 0 0 0 12 29 NA 44 45 B 46 31 Surveillance Test 80

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6 2 33 10 34 11 NA 44

AMOUNT OF ACTIVITY (35)

LOCATION OF RELEASE (36)

NA 45 80

PERSONNEL EXPOSURES									
NUMBER		TYPE		DESCRIPTION (39)					
1	7	0	0	0	(37)	Z	(38)	NA	

PERSONNEL INJURIES		DESCRIPTION	
NUMBER			
1	8	0	0
0	0	0	40
NA			

[illegible]

7	8	9	10											80						
PUBLICITY											NRC USE ONLY									
ISSUED											DESCRIPTION									
20											NA									
N											44									

NRC USE ONLY

NAME OF PREPARER W. F. Conway

PHONE: 802-257-7711

7910290358