



ARKANSAS POWER & LIGHT COMPANY  
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

October 25, 1979

2-109-21


Mr. K. V. Seyfrit, Director  
Office of Inspection & Enforcement  
U.S. Nuclear Regulatory Commission  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

Subject: Arkansas Nuclear One - Unit 2  
Docket No. 50-368  
License No. NPF-6  
License Event Report Nos. 79-075/03X-1;  
79-083/03L-0; 79-084/03L-0 and 79-085/03L-0  
(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.9b, we have attached the subject reports concerning the tripping of channel "B" of the CPC (LER 79-075/03X-1); the dropping of a CEA to the lower electrical limit (LER 79-083/03L-0 and LER 79-084/03L-0) and low boron concentration in the Refueling Water Tank (LER 79-085/03L-0).

Very truly yours,

  
for David C. Trimble  
Manager, Licensing

DCT:MAS:pw

Attachment

cc: Mr. Victor Stello, Jr., Director  
Office of Inspection & Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. W. D. Johnson  
U.S. Nuclear Regulatory Commission  
P.O. Box 2090  
Russellville, Arkansas 72801

Mr. Norman M. Haller, Director  
Office of Management and Program  
Analysis  
U.S. Nuclear Regulatory Comm.  
Washington, D. C. 20555

1244 197

7910310418