

0 1 1 C I M N S 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5  
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 33 34 CAT 56

CON'T

0 1 REPORT SOURCE L 6 0 5 0 0 0 3 3 6 7 0 9 2 9 7 9 8 1 0 2 5 7 9 9  
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During routine plant operations the Engineered Safety Features (ESF) channel A sensor  
0 3 cabinet trip bistables all tripped due to a loss of power. In accordance with technical  
0 4 specifications, section 3.3.2.1.b, the channel A ESF bistables were inhibited and  
0 5 plant operation continued while the failure was investigated and repaired. Total time  
0 6 out of service was 17 hours.

0 7

0 8

0 9 SYSTEM CODE I B 11 CAUSE CODE E 12 CAUSE SUBCODE G 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE X 15 VALVE SUBCODE Z 16  
7 8 9 10 11 12 13 14 15 16

17 LER/RO REPORT NUMBER 7 9 21 22 EVENT YEAR 7 9 23 24 SEQUENTIAL REPORT NO. 0 3 0 25 26 OCCURRENCE CODE 0 3 27 28 REPORT TYPE L 29 30 REVISION NO. 0 31 32  
ACTION TAKEN A 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED N 23 NPD-4 FORM SUB. Y 24 PRIME COMP. SUPPLIER A 25 COMPONENT MANUFACTURER 4 0 4 5 26  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause of the power failure was a failed over-voltage protector (Lambda, Model -  
1 1 LMOV-2) on the channel A -15 volt power supply which caused a fuse to blow. The  
1 2 over-voltage protector and fuse were replaced and the ESF channel A sensor cabinet  
1 3 was restored to operability.

1 4

1 5 FACILITY STATUS E 28 % POWER 1 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Observation 32  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 6 ACTIVITY CONTENT Z 33 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

2 0 PUBLICITY ISSUED N 44 DESCRIPTION NA 45  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

NAME OF PREPARER R. W. Bates

7911010401  
NRC USE ONLY  
203-447-1791  
68 69 80