

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

716 Edney Building

November 13, 1979

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

**TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET
NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE
REPORT NPRO-50-259/7829**

The enclosed report is a supplement to the letter from H. S. Fox dated October 25, 1978, concerning the cable raceway between the diesel generator building and the standby gas treatment building which appeared to have settled two inches at the diesel generator building end expansion joint during normal operation while installing additional cables. This report is submitted in accordance with Browns Ferry unit 1 Technical Specification 6.7.2.a(9).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

J. R. Calhoun
Director of Nuclear Power

POOR ORIGINAL

Enclosure (3)
cc (Enclosure):

Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

R. F. Sullivan, NRC Inspector, Browns Ferry

1347 004

Ass 2
5/1