



November 13, 1979

L79-1083

FILE: RR 2 (NP-33-79-118)

Docket No. 50-346  
License No. NPF-3

Mr. James G. Keppler  
Regional Director, Region III  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Reportable Occurrence 79-101  
Davis-Besse Nuclear Power Station Unit 1  
Date of Occurrence: October 17, 1979

Enclosed are three copies of Licensee Event Report 79-101 with a supplemental information sheet which is being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Terry D. Murray  
Station Superintendent  
Davis-Besse Nuclear Power Station

TDM/SNB/ljk

Enclosure

cc: Dr. Ernst Volgenau, Director  
Office of Inspection and Enforcement  
Encl: 30 copies LER 79-101

Mr. William G. McDonald, Director  
Office of Management Information  
and Program Control  
Encl: 3 copies LER 79-101

1345 337

7911190 516 5