

LICENSEE EVENT REPORT

CONTROL BLOCK:

						(1)
--	--	--	--	--	--	------------

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	A	L	J	M	F	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5	
7	8	LICENSEE CODE						14	LICENSE NUMBER												25	LICENSE TYPE					30	57 CAT		58

CONT

REPORT SOURCE	L	6	0	5	0	0	0	3	4	8	7	1	2	1	2	7	8	8	0	1	1	1	7	9	9
	60	61	DOCKET NUMBER						68	69	EVENT DATE						74	75	REPORT DATE						80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | At 1545 on 12/12/73 Train A river water (RW) pumps were observed to be in a tripped
0 3 | condition and could not be started from the Control Room. The pumps could be operated
0 4 | in local control. T/S 3.7.5 requires both RW loops operable. The Train A RW pumps
0 5 | were returned to an operable status at 2240 on 12/12/73. T/S 3.7.5 action statement
0 6 | requirements were met. The Train B RW pumps were operable. This occurrence had no
0 7 | effect on the health and safety of the public.

08 | _____ 80

09		SYSTEM CODE W E 11		CAUSE CODE E 12		CAUSE SUBCODE A 13		COMPONENT CODE R E L A Y X 14		COMP. SUBCODE K 15		VALVE SUBCODE Z 16	
7 8		9 10		11 12		13 14		15 16		17 18		19 20	
17		EVENT YEAR 7 8 21 22		SEQUENTIAL REPORT NO. 0 9 1 24 26		OCCURRENCE CODE 0 3 28 29		REPORT TYPE L 30		REVISION NO. 0 32			
ACTION TAKEN X 13 33		FUTURE ACTION X 19 34		EFFECT ON PLANT Z 20 35		SHUTDOWN METHOD Z 21 36		HOURS 0 0 0 0 22 37 40		ATTACHMENT SUBMITTED N 23 41		NPRD-4 FORM SUB. M 24 42	
										PRIME COMP. SUPPLIER A 25 43		COMPONENT MANUFACTURER G 0 5 0 26 44 47	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The exact cause of this occurrence has not been determined. LS511 was verified to be
1 1 operating properly. A similar event occurred on 11/25/78 and was reported in LER
1 2 78-088/03L-0. A test procedure has been developed and will be performed to simulate
1 3 the conditions that resulted in both occurrences. A supplemental report will be sub-
1 4 mitted to LER 78-088/03L-0 upon completion of the investigation.

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION		
1	5	E	1	0	0	NA	A							
7	8	9	10	11	12	13	14	15	16	17	18	19	20	

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)

1 6 7 (33) 2 (34) NA

7 8 9 10 11 44

LOCATION OF RELEASE (36)

NA

45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	37	Z	38	NA		39
2	8	9	11	12	13				

PERSONNEL INJURIES										
NUMBER				DESCRIPTION						
1	8	9	11	12						
0	0	0	40	JA						

LOSS OF OR DAMAGE TO FACILITY				(43)
TYPE		DESCRIPTION		
1	9	Z	(42)	NA
7	8	9	10	

790116821

PUBLICITY								NRC USE ONLY											
ISSUED		DESCRIPTION																	
	9	N	(44)	NA															

NAME OF PREPARER W. G. Hairston, III

PHONE: (205) 899-5156

NRC USE ONLY

000067.928