

CONTROL BLOCK:

--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	E	C	P	R	1	2	0	0	-	0	0	0	0	-	0	0	0	3	4	1	1	1	1	4			5		
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	LICENSE TYPE					30	CAT 58				

CON'T

REPORT SOURCE: 01 L 6 0 5 0 0 0 2 9 8 7 1 1 3 0 7 9 8 1 2 2 8 7 9 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During normal operation, suppression chamber level instrument PC-LI-12 failed down-

0	3
---	---

 scale. T.S. Table 3.2.F requires all level instruments operable. All other level

04 indicators were indicating properly. There were no significant occurrences as a

05 result of this event and there were no adverse affects to public health and safety.

06 This event is not repetitive.

08 _____

SYSTEM CODE I F 11		CAUSE CODE E 12		CAUSE SUBCODE E 13		COMPONENT CODE I N S T R U 14		COMP SUBCODE P 15		VALVE SUBCODE Z 16	
EVENT YEAR 7 9 21 22		SEQUENTIAL REPORT NO. 0 3 8 24 25 26		OCCURRENCE CODE / 27		REPORT TYPE L 30		REVISION NO. 0 32			
ACTION TAKEN C 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22 37 40		ATTACHMENT SUBMITTED N 23	
NPRD-4 FORM SUB. / 24		PRIME COMP. SUPPLIER N 25		COMPONENT MANUFACTURER S 3 3 3 26 44 47							

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The level indicator failed due to a failure of the power supply. The power supply is

11 a model CPS-15 24/28 manufactured by Standard Power Incorporated. The power supply

1 3 was replaced and proper indication was verified. The failure of the power supply was

1 3 | apparently due to an internal short, which caused the power supply transformer to

1	4	overheat and fail.
---	---	--------------------

8 9 FACILITY STATUS POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)

1 5 E (28) 0 9 3 (29) NA A (31) Failure of Indication

7 8 0 10 12 13 44 45 46 80

ACTIVITY CONTENT
RELEASED OF RELEASE

1 6 2 33 10 34

AMOUNT OF ACTIVITY (35)

NA

LOCATION OF RELEASE (36)

NA

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION	(39)				
1	7	0	0	0	(17)	Z	(38)	NA	

PERSONNEL INJURIES	(41)
NUMBER	DESCRIPTION
	POND ORIGINAL

0	0	0	40	NA	FOIA ORIGINAL	80
8	9	11	12			
LOSS OF OR DAMAGE TO FACILITY				43		
TYPE		DESCRIPTION				

1 9 2 42 NA 1024 257 80

PURCHASER'S COPY

ISSUED DESCRIPTION NA

NRC USE ONLY

NAME OF PREPARER David Phillips

PHONE 402-825-3811

NRC USE ONLY

0000