

NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 A R A N O 2 00-000000-000 41111 4 5
 7 8 9 14 15 25 26 30 37 CAT 58

CONT
01 L 05000368 122179 012980
 7 8 9 14 15 25 26 30 37 CAT 58

REPORT SOURCE L 05000368 122179 012980
 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
02 During Mode 1 operation, "C" Core Protection Calculator failed. All
03 remaining CPC channels remained operable. The channel "C" DNBR and
04 LPD trips were by passed placing the reactor trip logic in a 2 out of 3
05 trip sequence. This occurrence is similar to LER 50-368/79-082.
06 Reportable Per Tech. Spec. 6.9.1.9.b.
07
08
09

SYSTEM CODE IA 11 CAUSE CODE E 12 CAUSE SUBCODE E 13 COMPONENT CODE INSTRU 14 COMP SUBCODE Y 15 VALVE SUBCODE Z 16
 9 10 11 12 13 14 15 16

LER NO REPORT NUMBER 79 1 SEQUENTIAL REPORT NO 102 OCCURRENCE CODE 03 REPORT TYPE X REVISION NO 1
 17 21 22 23 24 25 26 27 28 29 30 31 32

ACTION TAKEN A 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0000 ATTACHMENT SUBMITTED N 23 NPD-4 FORM SUB N 24 PRIME COMP SUPPLIER N 25 COMPONENT MANUFACTURER C490 26
 33 34 35 36 37 38 39 40 41 42 43 44 45

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
10 A failed RCP speed input to the CPC channel caused the failure.
11 Thirty (30) minutes later the speed input returned to normal DNBR and
12 LPD trips were returned to their functional positions within 3 hours
13 per T.S. Table 3.3.1. Action 2a. The speed probe and cable were replaced during
14 the following outage to prevent this intermittent failure reoccurrence.
15

FACILITY STATUS B 28 % POWER 080 29 OTHER STATUS 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION 32
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

ACTIVITY CONTENT Z 33 RELEASED OF RELEASE Z 34 AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

PERSONNEL EXPOSURES NUMBER 000 37 TYPE Z 38 DESCRIPTION 39
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

PERSONNEL INJURIES NUMBER 000 40 DESCRIPTION 41
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION 43
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

PUBLICITY ISSUED DESCRIPTION 45
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

ISSUED N 44 NA
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

NAME OF PREPARER Rex Pendergraft PHONE: 501/968-2519

1876 105

8002050504