



January 31, 1979

L79-036

FILE: RR 2 (NP-33-79-05)

Docket No. 50-346
License No. NPF-3

Mr. James G. Keppler
Regional Director, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Reportable Occurrence 79-004
Davis-Besse Nuclear Power Station Unit 1
Date of Occurrence: January 5, 1979

Enclosed are three copies of Licensee Event Report 79-004 with a supplemental information sheet which is being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Terry D. Murray

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/SNB/ljk

Enclosure

cc: Dr. Ernst Volgenau, Director
Office of Inspection and Enforcement
Encl: 30 copies LER 79-004

Mr. William G. McDonald, Director
Office of Management Information
and Program Control
Encl: 3 copies LER 79-004

790206-0323