

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[illegible]

Georgia Power Company
Plant E. I. Hatch
Baxley, Georgia 31513

Reportable Occurrence No. 50-321/1979-4

Cause Description (cont.)

verified to have no deviations from the elementary diagram per procedure HNP-6927 (Motor Failure Checkout). The motor was reinstalled, after it was rewound, and procedure HNP-1-3302 performed satisfactorily.