

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	1	L	Q	A	D	1	2	0	0	0	-	0	0	0	-	0	0	0	3	4	1	1	1	1	4			5	
7	8	9	LICENSEE CODE					14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	58

REPORT
SOURCE

REPORT SOURCE: 01 L 6 0 5 0 0 0 2 5 4 7 0 1 2 2 7 9 8 0 2 1 6 7 9 9

7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While performing local leak rate testing, the containment purge volume bounded by
03 valves A0 1-1601-21, 22, 55, 56 was found to have a leak rate of 58.3 SCFH. Further
04 testing of the volume showed that the majority of the leakage was through valve
05 A0 1-1601-55. The safety implications of this event are minimal since valves A0
06 1-1601-21, 22, 56 were within acceptable leakage limits. The volume would have
07 isolated properly when needed.

[illegible]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The full closing stroke of the valve operator did not permit enough stem travel to

1 1 allow the valve disc to fully contact the valve seat. This conditon resulted in

1 2 leakage past the valve seat. The valve operator stroke was lengthened and the valve

1 3 retested. The corrected leak rate for the volume was found to be 14.5 SCFH.

1 4

FACILITY STATUS (28) 1 5 H
 % POWER 0 0 0 (29) NA
 OTHER STATUS (30)
 METHOD OF DISCOVERY (31) B
 DISCOVERY DESCRIPTION (32) Local Leak Rate Testing

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)
1 6 2 33 2 34 NA
7 8 9 10 11 44

LOCATION OF RELEASE (36)
NA 45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37)	Z	(38)	NA	(39)

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	40 NA

1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
1		2		3		4		5		6		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52																																																									

7903070346

PUBLICITY

ISSUED DESCRIPTION (45)

2 0 N (44) NA

68 69 80

NRC USE ONLY

NAME OF PREPARER M. Kooi

PHONE: 309-654-2241, ext. 252