

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	-	0	3	2	4	7	0	5	2	1	7	9	8	0	6	1	5	7	9	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	9		R	B	11	A	12	X	13	Z	Z	Z	Z	Z	Z	14	Z	15	Z	16			
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20				
LER/RO REPORT NUMBER		EVENT YEAR				SEQUENTIAL REPORT NO.				OCCURRENCE CODE		REPORT TYPE				REVISION NO.							
17		7	9			0	3	5			0	3	L			0							
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER							
X	18	G	19	Z	20	Z	21	0	0	0	0	22	Y	23	Y	24	N	25	G	0	8	0	26
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

FACILITY STATUS (1) 5 (2) G (28) 0 0 0 0 (29) NA (30) OTHER STATUS
 METHOD OF DISCOVERY (31) A (32) Modification Review
 ACTIVITY CONTENT (33) Z (34) Z (35) NA (36) LOCATION OF RELEASE
 RELEASED OF RELEASE (37) 0 0 0 (38) Z (39) NA
 PERSONNEL EXPOSURES (40) 0 0 0 (41) Z (42) NA
 PERSONNEL INJURIES (43) 0 0 0 (44) Z (45) NA
 LOSS OF OR DAMAGE TO FACILITY (46) Z (47) NA
 PUBLICITY (48) N (49) NA
 ISSUED (50) N (51) NA
 7906220375
 NRC USE ONLY

NAME OF PREPARER

A. C. Tollison, Jr.

PHONE

919-457-6701

LER CONTINUATION -- RO# 2-79-035

Facility: BSEP Unit No. 2

Event Date: 5-21-79

limits. Total time above 30% power was approximately 24 hours, with the highest power approximately 48%.

2347 323