

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	C	B	E	P	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	9						14	15	25										26	30				57	58			
		LICENSEE CODE							LICENSE NUMBER											LICENSE TYPE				CAT					

REPORT

0 1 7 8

REPORT SOURCE

L 6 0 5 0 - 0 3 2 4 7 0 5 1 9 7 9 8 0 6 1 8 7 9 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During a review of startup data following a reactor startup, it was noted that

03 PT 2.6.5, Primary Containment Leak Rate Test on the Airlock, was not completed within

04 | the required 72 hours after reaching condition 3. Condition 3 was reached at 0640 on

05 May 14, 1979 and the leak rate test was not done until May 19, 1979, for a total

06 elapsed time of approximately 133 hours.

07 (Technical Specifications 3.6.1.3, 6.9.1.9c)

08 | _____ 8

0	9	SYSTEM CODE S A		11	CAUSE CODE A		12	CAUSE SUBCODE A		13	COMPONENT CODE Z Z Z Z Z Z					14	COMP. SUBCODE Z		15	VALVE SUBCODE Z		16	
7	8			9	10			11			12						13			15			16
17		LER/RO REPORT NUMBER		EVENT YEAR 7 9		QUANTAL REPORT NO. 0 3 9		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0											
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER							
X		Z		Z		Z		0 0 0 0		N		N		A		Z 9 9 9							
33		34		35		36		37		40		41		42		43		44		47			

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 PT 2.6.5 was completed satisfactorily on the airlock. During this period of operation,

1 1 | an administrative oversight prevented the detection of PT 2.6.5 not having been per-

1 2 formed. The plant startup procedure GP-1 has been revised such that PT 2.6.5 must be

13 completed before the reactor is taken critical.

1	4		
7	8	9	80

FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)

1 5 E (28) 0 2 0 (29) NA A (31) Operator Log Review

7 8 9 10 12 13 44 45 46 80

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)

1 6 Z (33) Z (34) NA

7 8 9 10 11 44

LOCATION OF RELEASE (36)

NA

45 80

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	0	0	0	(37) Z (38) NA (39)				

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	NA

LOSS OF OR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION
1 9 Z (42) NA 7906220400 J

PUBLICATION		ISSUED		DESCRIPTION		NRC USE ONLY	
2	0	N	(44)	NA	(45)		

NAME OF PREPARER A. C. Tollison, Jr.

PHONE: 919-457-6701