

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
500C Chestnut Street Tower II

JUN 18 1979

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNITS 1 AND 2 - PIPE RESTRAINT STRUCTURAL
STRAND TEMPERATURE - NCR MEB 79-18 - FINAL REPORT

The subject deficiency was initially reported to NRC-OIE
inspector, Don Quick, on May 17, 1979, in accordance with
10 CFR 50.55(e). Enclosed is our final report.

If you have any questions concerning this matter, please get
in touch with D. L. Lambert at FTS 854-2581.

Very truly yours,

J. E. Gilleland
Assistant Manager of Power

Enclosure

cc: Mr. John G. Davis, Acting Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

2238 251

7906250269

B019
S/11