

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Shaw Pipeline Services, Inc.
1644 Blue Horizon Drive, Morgantown, WV, and
TJS at 1007 Meadowbrook Road, Bridgeport, WV

REPORT NO.: 2019-003

2. NRC/REGIONAL OFFICE

U.S. Nuclear Regulatory Commission
Region IV, 1600 East Lamar Blvd
Arlington, Texas 76011-4511

3. DOCKET NUMBER

030-38558

4. LICENSE NUMBER

35-23193-03

5. DATE(S) OF INSPECTION

July 22 and 24, 2019

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☒ 1. Based on the inspection findings, no violations were identified.
- ☒ 2. Previous violation(s) closed. **(IR 2019-002)**
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.
- ☐ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):
- ☐ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Leonardo Wardrobe		8/20/19
BRANCH CHIEF	Patricia A. Silva		8/23/19

☐

Non-Public

☐

Sensitive – Security-Related

☒

Public

☒

Non-Sensitive

From: [Chad Teeters](#)
To: [VonEhr, Jason](#)
Subject: [External_Sender] RE: NRC Inspection Report - Shaw Pipeline Services
Date: Wednesday, August 21, 2019 9:38:45 AM

I have received the inspection report.

Thank you

From: VonEhr, Jason <Jason.VonEhr@nrc.gov>
Sent: Wednesday, August 21, 2019 9:21 AM
To: Chad Teeters <Chad.Teeters@shawcor.com>
Subject: NRC Inspection Report - Shaw Pipeline Services

External Sender – be cautious with links and attachments contained within this email.
Mr. Chad Teeters,

I'd like to thank you for your time today and your staff during the NRC inspection at your facility in Morgantown, WV, on July 22, 2019, and at the temporary job site in Bridgeport, WV, on July 22 & 24, 2019. As I briefly discussed today, the NRC has determined that no violations were identified. The attached NRC Inspection Report (NRC Form 591M) documents the results of the inspection. This does not require you to take any action and you are not required to sign the document or return it. I do however request a courtesy email response from you acknowledging receipt.

If you have any questions or concerns, please do not hesitate to contact me,

--

Jason vonEhr
Health Physicist
U.S. Nuclear Regulatory Commission, Region-IV
1600 East Lamar Boulevard
Arlington, Texas 76011-4511

Office: (817) 200-1186
Fax: (817) 200-1083
Email: jason.vonehr@nrc.gov



The information contained in this message may be privileged and/or confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please notify the sender immediately by replying to the message and deleting the material from any computer.

Note: Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of the Nuclear Regulatory Commission, Region-IV or the Materials Inspection Branch. All e-mails are subject to monitoring and archival.

Finally, the recipient should check this message and any attachments for the presence of viruses. The Nuclear Regulatory Commission accepts no liability for any damage caused by any virus transmitted by this e-mail.