

# LICENSEE EVENT REPORT

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | 1 L Q A D 1 2 | d d d - 0 0 0 - 0 0 0 3 | 4 1 1 1 1 4 | 5

IDENT

1 | L 5 0 5 0 0 2 5 4 7 | 0 2 1 7 7 9 9 | 0 3 1 4 7 9 0

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

1 2 | While performing Excess Flow Check Valve Surveillance, procedure QIS 47-1, check  
3 | valves 1-263-2-31B and 1-263-42A failed to check the flow through the instrument  
4 | lines. Each line has a manual isolation valve upstream from the flow check valves  
5 | which could have isolated the flow if the need arose. The failure of the check  
6 | valves to limit instrument line flow did not hinder the operation of the associated  
7 | instruments.

SYSTEM CODE S D 1 | CAUSE CODE E 12 | CAUSE SUBCODE B 13 | COMPONENT CODE V A L V E X 14 | COMP SUBCODE C 15 | VAL SUBCODE G 16  
 LER/RO REPORT NUMBER 7 9 | EVENT YEAR 7 9 | SHUTDOWN METHOD Z 21 | SEQUENTIAL REPORT NO. 0 1 3 | OCCURRENCE CODE 0 3 | REPORT TYPE L 30 | REVISION NO. 0 32  
 ACTION TAKEN D 18 | FUTURE ACTION Z 19 | EFFECT ON PLANT Z 20 | HOURS 0 0 0 0 22 | ATTACHMENT SUBMITTED N 23 | NPRD-4 FORM SUB. Y 24 | PRIME COMP. SUPPLIER N 25 | COMPONENT MANUFACTURER C 2 9 5 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 | The apparent cause of this event was an accumulation of dirt on the valve internals,  
1 1 | enhanced by low flow conditions and by the fact that these valves do not change  
1 2 | position during normal plant operation. The valve internals were removed, cleaned  
1 3 | and reassembled. The valves were then successfully tested. A previous failure of this  
1 4 | type occurred on March 5, 1978, and was reported in LER/RO 78-14/03L.

FACILITY STATUS H 28 | POWER L 0 0 29 | OTHER STATUS NA 30 | METHOD OF DISCOVERY B 31 | DISCOVERY DESCRIPTION Surveillance Test 32  
 ACTIVITY CONTENT RELEASED Z 33 | AMOUNT OF ACTIVITY NA 35 | LOCATION OF RELEASE NA 36  
 PERSONNEL EXPOSURES NUMBER 0 0 0 37 | TYPE Z 38 | DESCRIPTION NA 39  
 PERSONNEL INJURIES NUMBER 0 0 0 40 | DESCRIPTION NA 41  
 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 | DESCRIPTION NA 43  
 PUBLICITY N 44 | DESCRIPTION NA 45

7903280355

NRC USE ONLY

NAME OF PREPARER

J. Kopacz

PHONE

309-654-2241, ext. 248