

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

500C Chestnut Street Tower II

on MAR 5 ~~March 8, 1979~~

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNITS 1 AND 2 - ERROR IN DESIGN OF SMALL LINE
SUPPORTS - NCR SWP 79-S-1 - FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
McKensie Thomas on February 5, 1979. Enclosed is our final report.

If you have any questions concerning this matter, please get in touch
with M. R. Wisenburg at FTS 854-2581.

Very truly yours,



J. E. Cilleland

Assistant Manager of Power

Enclosure

cc: Mr. John G. Davis, Acting Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

7904060247

B019
S/11

790137