

FEDERAL NOTIFICATION LETTER

Wednesday, September 25, 2019

Director of FSME
Attn: GLTS
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

This letter is a notification per 10 CFR 31.5(c)(8) or corresponding State regulation indicating that a device containing radioactive material was transferred from a general licensee to a specific licensee. The following information is provided:

From General Licensee:

Minnetrista
1200 N. Minnetrista Parkway
Muncie, IN 47303

To Specific Licensee:

SRB Technologies, Inc.
2580 Landmark Drive
Winston-Salem, NC 27103
(336)-659-2610
Radioactive Materials License #034-0534-2

Date of Transfer: (Enter Date Disposal Box was shipped to Specific Licensee)	October 8, 2019
--	-----------------

Description of Device(s) Transferred:

Exit signs containing tritium as per attached Inventory Form(s).

If there are questions or concerns, please contact me.

Sincerely,

Printed Name:	Randy Gowin
Signature:	Randy Gowin
Phone Number:	765 287 3565

FEDERAL LETTER- MAIL TO USNRC WITHIN 30 DAYS OF SHIPMENT

NM5510

VEOLIA USE ONLY

Sales Order #: 2106068
Case #: 00027508
Box 1 of 1

VEOLIA USE ONLY

RGA #: 998002
RGA # Expiration Date: 12/20/19
UCN: 5W51382X-8Y55606Z
Fedex Tracking #: 691191700755782

TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. **DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMATION.** Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

	DESCRIPTION/MFR.	MODEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT or LIFE RATING
1.	ISOLITE	2000	A551046	5/95	7.5
2.	ISOLITE	2000	A551047	5/95	7.5
3.	ISOLITE	2000	A551054	5/95	7.5
4.	ISOLITE	2000	A551063	5/95	7.5
5.	ISOLITE	2000	A551064	5/95	7.5
6.	ISOLITE	2000	A551065	5/95	7.5
7.	ISOLITE	2000	A551066	5/95	7.5
8.	ISOLITE	2000	A551067	5/95	7.5
9.	ISOLITE	2000	A551068	5/95	7.5
10.	ISOLITE	2000	A551069	5/95	7.5

Describe any damaged units:
Please email pictures of damaged signs to
pak.ts@veolia.com

I hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.

GENERATOR CERTIFICATION

Generator Signature:

Randy Gowin

Title:

Maintenance Manager

Print Name:

Randy Gowin

Date:

9/13/2019

VEOLIA INFORMATION - DO NOT WRITE IN THIS BOX

Date Received:

9-13-19

Checked in by:

Angie Kung