

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37417

1750 Chestnut Street Tower II

May 20, 1981

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET
NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE
REPORT BFRO-50-259/81014

The enclosed report provides details concerning main steam isolation
valves 1-14, 1-15, 1-26, 1-27, 1-37, 1-38, 1-51, and 1-52 which when
tested exceeded the allowable leak rate of 11.5 standard cubic feet per
hour. This report is submitted in accordance with Browns Ferry unit 1
Technical Specification 6.7.2.b(4).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. J. Green
Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. Bill Lavallee
Nuclear Safety Analysis Center
Palo Alto, California 94303

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

A002
S
1/1

810527 0233
S