

## (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

03

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION

ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY	LOCATION OF RELEASE
1	6	7	33	7	34
				NA	NA

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION	
1	7	0	0	0	NA

[illegible]

LOSS OF OR DAMAGE TO FACILITY (43)

TYPE		DESCRIPTION
1	9	NA

8 9 10  
PUBLICITY  
ISSUED DESCRIPTION (45) NA  
8106010515  
NRC USE ONLY

# POOR ORIGINAL

PHONE: (205) 899-5156

LER NO. 81-028/03L-0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (Continued)

during plant heatups.

Alarm setpoints (low and high) currently coincide with Technical Specification limits. A review will be conducted to determine desirability of revising the alarm setpoints to slightly above and below the low and high Technical Specification limits respectively in order to receive the alarm without violating the Technical Specification requirements.