

CONTROL BLOCK: 

--	--	--	--	--	--

 ①

0	1	N	Y	J	A	F	1	2	0	0	-	0	0	0	0	-	0	0	0	3	4	1	1	1	1	1	4	5				
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57 CAT 58				

CON'T

0	1	REPORT SOURCE										EVENT DATE										REPORT DATE																
7	8	L	6	0	5	10	10	0	3	3	3	7	0	5	0	5	8	1	3	0	6	0	3	8	1	4												
		60	61	DOCKET NUMBER										68	69	EVENT DATE										74	75	REPORT DATE										80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | During normal shutdown operations, while conducting surveillance of instruments  
03 | used to satisfy TS 4.5.A.3, RHR flow indicator 10-FI-133A was found out of  
04 | calibration in the non-conservative direction. The instrument was out of  
05 | calibration such that it indicated 18,300 gpm when it should have indicated  
06 | between 17,000 and 18,200 gpm. No significant hazard existed.

0 7 | \_\_\_\_\_

0 8 | \_\_\_\_\_

7 8 9 3

7 8 9

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE

0 9 11 12 13 14 15 16

7 8 9 10 11 12 13 14 15 16 17 18 19 20

(17) LER RO REPORT NUMBER 81 — SEQUENTIAL REPORT NO. 040 / OCCURRENCE CODE 03 REPORT TYPE L — NO. 0

ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRO-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER						
E	18	Z	19	Z	21	0000	N	23	Y	24	N	25	G	0	8	0
32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The cause is believed to be instrument drift. The instrument was immediately

1 1 recalibrated to within procedural tolerance. No additional action is required.

1	2	
---	---	--

1	3
---	---

1	4	
---	---	--

7 8 9  
FACILITY STATUS (28) 1 5 G  
% POWER (29) 0 0 0  
OTHER STATUS (30) NA  
METHOD OF DISCOVERY (31) B  
DISCOVERY DESCRIPTION (32) Surveillance

ACTIVITY CONTENT  
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 7 2 33 10 7 34 NA NA NA

PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION
1	7	000	(37) Z (38)	NA

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	2	0	0	0	40 NA

1		2		3		4		5		6		7		8		9		10		11		12	
LOSS OF OR DAMAGE TO FACILITY (43)																							
TYPE DESCRIPTION																							
1		2		3		4		5		6		7		8		9		10		11		12	
Z		(42)																					
NA																							

7 8 9 10  
PUBLICITY  
ISSUED DESCRIPTION (45)  
2 0 N (44) NA  
68 69

NRC USE ONLY

8106090

NAME OF PREPARER W. Verne Childs

PHONE 315-342-3840