

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

81-038-032
WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

April 16, 1981

TELEPHONE: AREA 704
373-4083


Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 1
Docket No. 50-369

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/81-32. This report concerns the operability of various portions of the fire detection system. These occurrences were considered to be of no significance with respect to the health and safety of the public.

Very truly yours,


William O. Parker, Jr.

RWO/mwk
Attachment

cc: Director
Office of Management and Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. Bill Lavallee
Nuclear Safety Analysis Center
Post Office Box 10412
Palo Alto, California 94303



IE22
5/1

8106290 231 S